EXHIBIT G-2 THIS REPORT PREPARED PURSUANT TO DUTY IMPOSED BY A.A.C. R13-10-104 (A)

ARIZONA DEPARTMENT OF PUBLIC SAFETY

STANDARD QUALITY ASSURANCE PROCEDURES INTOXILYZER MODEL 8000

STANDARD CALIBRATION CHECK PROCEDURE

QA SPECIALIST W. T. RYAN # 1100 AGENCY GOUDYEAR PULICE DEPT
DATE 12-15-16 TIME 0028 HOC
INTOXILYZER SERIAL # 80 - OO 1858 LOCATION // U.S. LIKHELELD OF COMP
1. Ensure that gas tank is attached to instrument and contains a standard alcohol concentration solution 0,100 AC
simulator. Ensure that a tight seal has been made. Turn on the simulator and allow temperature to reach 34°C +
2. Intoxityzer 8000 display reads "PUSH BUTTON TO START" 3. Go to the "Control Testing Menu". Select "D" for dry control test or "W" for wet control test. After selection is made press ENTER.
4. Air blank completed. 5. Calibration check completed. Test results 0. 099 AC. 6. Air blank completed. 7. Remove printed record. Attach the record to the completed checklist.
7. Remove printed record. Attach the record to the completed checklist.
SIGNATURE W. T. Reya 1100
DPS Form Exh G-2 (Rev 05-01)

INTOXILYZER 8000

Location: 1111 S LITCHFIELD RD

Serial Number: 80-001858 Core Version: 8105.48

12/15/2016 00:38:38

Standard Lot#: 28515100A1 Last Changed By: W. RYAN #1100

QAS: W. RYAN #1100

GOODYEAR PD

Operator: W. RYAN #1100

GOODYEAR PD

Test	g/210L	Time
Air Blank	0.000	00:39:09
0.100 Cal Check	0.099	00:39:30
Air Blank	0.000	00:40:00

Preventative Maintenance Performed -- Timer Reset