## EXHIBIT G-2 THIS REPORT PREPARED PURSUANT TO DUTY IMPOSED BY A.A.C. R13-10-104 (A)

## ARIZONA DEPARTMENT OF PUBLIC SAFETY

## STANDARD QUALITY ASSURANCE PROCEDURES INTOXILYZER MODEL 8000

## STANDARD CALIBRATION CHECK PROCEDURE

QA SPE	CIALIST W. T. RYAN 1100 AGENCY GOODY GAR P.D.
DATE_	5-23-14 TIME 1112
IXOTAI	LYZER SERIAL # 80-001858 LOCATION [1] S LITCHFIELD BO GOUDY GAM
(S) 1	. Ensure that gas tank is attached to instrument and contains a standard alcohol concentration solution O. 100 AC.
	Pour a standard alcohol concentration solutionAC, into a clean dry simulator and assemble the simulator. Ensure that a tight seal has been made. Turn on the simulator and allow temperature to reach 34°C ± 0.2°C
(J) 3	Intoxilyzer 8000 display reads "PUSH BUTTON TO START"  Go to the "Control Testing Menu". Select "D" for dry control test or "W" for wet control test. After selection is made press ENTER.
(S) 4 (S) 5 (S) 6	Air blank completed. Calibration check completed. Test results 0. 098 AC. Air blank completed.
(V) 7	. Remove printed record. Attach the record to the completed checklist.
SIGNAT	URE W.T. Vaga /100
DPS For	m Exh G-2 (Rev 05-01)

INTOXILYZER 8330

Location: !!!! S LITCHFIELD RD

Serial Number: 80-001858 Core Uersion: 8105.48

05/23/2014

11:12:24

Standard Lot#: 32012100A1

Last Changeo By: W. W!LL #974

OAS: W. RYAN #1100

GOODYEAR PD

Operator: W. RYAN #1100

GOODYEAR PD

Test g/210L Time

Air Blank 0.000 11:13:11
0.100 Cal Check 0.098 11:13:31
Air Blank 0.000 11:14:01

Preventative Maintenance Performed -- Timer Reset