EXHIBIT G-2 THIS REPORT PREPARED PURSUANT TO DUTY IMPOSED BY A.A.C. R13-10-104 (A)

ARIZONA DEPARTMENT OF PUBLIC SAFETY

STANDARD QUALITY ASSURANCE PROCEDURES INTOXILYZER MODEL 8000

STANDARD CALIBRATION CHECK PROCEDURE

QA SPECIALIST W. T. RYAN 1100 AGENCY GOODYGAR P.D.
DATE 11-26-14 TIME 2007
INTOXILYZER SERIAL # 80-000312 LOCATION [1] S LITCHFIELD PO GOODYGAL AZ
1. Ensure that gas tank is attached to instrument and contains a standard alcohol concentration solution OR
Pour a standard alcohol concentration solutionAC, into a clean dry simulator and assemble the simulator. Ensure that a tight seal has been made. Turn on the simulator and allow temperature to reach 34°C ± 0.2°C
 Intoxilyzer 8000 display reads "PUSH BUTTON TO START" Go to the "Control Testing Menu". Select "D" for dry control test or "W" for wet control test. After relection in
made press ENTER. 4. Air blank completed. 5. Calibration check completed. Test results 0. LO AC. 6. Air blank completed. 7. Remove printed record. Attach the record to the completed checklist.
7. Remove printed record. Attach the record to the completed checklist. SIGNATURE W. T. Rugar 1100
DPS Form Exh G-2 (Rev 05-01)

NO PROBLEMS

INTOXILYZER 8000

Location: 1111 S LITCHFIELD RD

Serial Number: 80-000312 Core Version: 8105.48

11/26/2014 20:07:19

Standard Lot#: 25913100A2 Last Changed By: W. RYAN #1100

QAS: W. RYAN #1100

GOODYEAR PD-

Operator: W. RYAN #1100

GOODYEAR PD

Test	g/210L	Time
Air Blank	0.000	20:08:20
0.100 Cal Check	0.101	20:08:41
Air Blank	0.000	20:09:11

Preventative Maintenance Performed -- Timer Reset

pstan3