EXHIBIT G-2 THIS REPORT PREPARED PURSUANT TO DUTY IMPOSED BY A.A.C. R13-10-104 (A)

ARIZONA DEPARTMENT OF PUBLIC SAFETY

STANDARD QUALITY ASSURANCE PROCEDURES INTOXILYZER MODEL 8000

STANDARD CALIBRATION CHECK PROCEDURE

QA SPECIALIST W. T. RYAN # 1100 AGENCY GOODYGAR POUCE DEPT
DATE 4-12-2015 TIME 0240
INTOXILYZER SERIAL # 80-001858 LOCATION III S LITCHFIELD RO GOODYGIR A
1. Ensure that gas tank is attached to instrument and contains a standard alcohol concentration solution OR
Pour a standard alcohol concentration solutionAC, into a clean dry simulator and assemble the simulator. Ensure that a tight seal has been made. Turn on the simulator and allow temperature to reach 34°C ± 0.2°C
2. Intoxilyzer 8000 display reads "PUSH BUTTON TO START" 3. Go to the "Control Testing Menu". Select "D" for dry control test or "W" for wet control test. A for colorier is
3. Go to the "Control Testing Menu". Select "D" for dry control test or "W" for wet control test. After selection is made press ENTER.
4. Air blank completed.
() S Collibration shock completed Test and O O O
6. Air blank completed. 7. Remove printed record. Attach the record to the completed checklist.
7. Remove printed record. Attach the record to the completed checklist.
SIGNATURE W. T. Rayon # 1100
DPS Form Exh G-2 (Rev 05-01)

INTOXILYZER 8000

Location: 1111 S LITCHFIELD RD

Serial Number: 80-001858 Core Version: 8105.48

04/12/2015 02:40:07

Standard Lot#: 25913100A2

Last Changed By: W. RYAN #1100

QAS: W. RYAN #1100

GOODYEAR PD

Operator: W. RYAN #1100

GOODYEAR PD

Test	g/210L	Time
Air Blank	0.000	02:40:40
0.100 Cal Check	0.099	02:41:01
Air Blank	0.000	02:41:31

Preventative Maintenance Performed -- Timer Reset