## EXHIBIT G-2 THIS REPORT PREPARED PURSUANT TO DUTY IMPOSED BY A.A.C. R13-10-104 (A)

## ARIZONA DEPARTMENT OF PUBLIC SAFETY

## STANDARD QUALITY ASSURANCE PROCEDURES INTOXILYZER MODEL 8000

## STANDARD CALIBRATION CHECK PROCEDURE

QA SPECIALIST W. T. RYW # 1100 AGENCY GOODYER P.D.			
DATE 6-27-15 TIME 1/25			
INTOXILYZER SERIAL # 80-000312 LOCATION IIII S CHCHETEO PO GOODY			
1. Ensure that gas tank is attached to instrument and contains a standard alcohol concentration solution OR			
Pour a standard alcohol concentration solutionAC, into a clean dry simulator and assemble the simulator. Ensure that a tight seal has been made. Turn on the simulator and allow temperature to reach 34°C ± 0.2°C			
<ol> <li>Intoxilyzer 8000 display reads "PUSH BUTTON TO START"</li> <li>Go to the "Control Testing Menu". Select "D" for dry control test or "W" for wet control test. After selection is made press ENTER.</li> </ol>			
<ul> <li>4. Air blank completed.</li> <li>5. Calibration check completed. Test results 0. OO AC.</li> <li>6. Air blank completed.</li> </ul>			
7. Remove printed record. Attach the record to the completed checklist.			
SIGNATURE W. T. Page 1100			
DPS Form Exh G-2 (Rev 05-01)			

NO PROBLEMS NOTED

INTOXILYZER 8000

Location: 1111 S LITCHFIELD RD

Serial Number: 80-000312 Core Version: 8105.48

06/27/2015

11:25:10

------

Standard Lot#: 26614100A6

Last Changed By: W. RYAN #1100

QAS: W. RYAN #1100

GOODYEAR PD

-----

Operator: W. RYAN #1100

GOODYEAR PD

.

Test	g/210L	Time
Air Blank	0.000	11:25:49
0.100 Cal Check	*****	11:26:10
Air Blank	0.000	11:26:40

Preventative Maintenance Performed -- Timer Reset