## EXHIBIT G-2 THIS REPORT PREPARED PURSUANT TO DUTY IMPOSED BY A.A.C. R13-10-104 (A)

## ARIZONA DEPARTMENT OF PUBLIC SAFETY

## STANDARD QUALITY ASSURANCE PROCEDURES INTOXILYZER MODEL 8000

## STANDARD CALIBRATION CHECK PROCEDURE

QA SPECIALIST W. T. RYAN 1100 AGENCY GOODY FOR P.D.
DATE 9-19-2015 TIME 1656
INTOXILYZER SERIAL # 80 - 000312 LOCATION 1111 S LICHTICA B GOODYGAR 1
1. Ensure that gas tank is attached to instrument and contains a standard alcohol concentration solution OR  Pour a standard alcohol concentration solution AC, into a clean dry simulator and assemble the simulator. Ensure that a tight seal has been made. Turn on the simulator and allow temperature to reach 34°C ± 0.2°C  2. Intoxilyzer 8000 display reads "PUSH BUTTON TO START"  3. Go to the "Control Testing Menu". Select "D" for dry control test or "W" for wet control test. After selection is made press ENTER.  4. Air blank completed.  5. Calibration check completed. Test results 0. 100 AC.  6. Air blank completed.  7. Remove printed record. Attach the record to the completed checklist.  SIGNATURE  SIGNATURE  100
DPS Form Exh G-2 (Rev 05-01)
NO ISSUES
STANDARD CHANGE ALSO

INTOXILYZER 8000

Location: 1111 S LITCHFIELD RD

Serial Number: 80-000312 Core Version: 8105.48

09/19/2015 16:56:21

-----

Standard Lot#: 16014100A1 Last Changed By: W. RYAN #1100

\_\_\_\_\_\_

QAS: W. RYAN #1100 .

GOODYEAR PD

Operator: W. RYAN #1100

GOODYEAR PD

-----

Test	g/210L	Time
Air Blank	0.000	16:57:09
0.100 Cal Check	0.100	16:57:29
Air Blank	0.000	16:58:00

Preventative Maintenance Performed -- Timer Reset