EXHIBIT G-2 THIS REPORT PREPARED PURSUANT TO DUTY IMPOSED BY A.A.C. R13-10-104 (A)

ARIZONA DEPARTMENT OF PUBLIC SAFETY

STANDARD QUALITY ASSURANCE PROCEDURES INTOXILYZER MODEL 8000

STANDARD CALIBRATION CHECK PROCEDURE

QA SPECIALIST W. T. RYAN #1/00 AGENCY GOODYGAR POLICE DEP-
TIME 1723
INTOXILYZER SERIAL # 80 - 000312 LOCATION 11 N 145TH AVE GOODFAR AS
1. Ensure that gas tank is attached to instrument and contains a standard alcohol concentration solution OP AC.
Pour a standard alcohol concentration solutionAC, into a clean dry simulator and assemble the simulator. Ensure that a tight seal has been made. Turn on the simulator and allow temperature to reach 34°C ± 0.2°C
 Intoxilyzer 8000 display reads "PUSH BUTTON TO START" Go to the "Control Testing Menu". Select "D" for dry control test or "W" for wet control test. After selection is made press ENTER.
4. Air blank completed. 5. Calibration check completed. Test results 0. 096 AC. 6. Air blank completed.
/. Remove printed record. Attach the record to the completed checklist.
SIGNATURE W. T. Reyon 1100
OPS Form Exh G-2 (Rev 05-01)

INTOXILYZER 8000
Location: 11 N 145TH AUE
Serial Number: 80-000312
Core Version: 8105.48
04/05/2018 17:23:54

Standard Lot#: 14816100A1
Last Changed By: W. RYAN #1100

OAS: W. RYAN #1100
GOODYEAR PD

Test g/210L Time

Air Blank 0.000 17:24:25
0.100 Cal Check 0.096 17:24:46
Air Blank 0.000 17:25:16

Preventative Maintenance Performed -- Timer Reset