

## ARIZONA DEPARTMENT OF PUBLIC SAFETY

## INTOXILYZER SERVICE REQUEST

SEND ALL COPIES TO DPS CRIME LABORATORY

		QUALITY	ASSURANCE SPECIAL	IST			
DATE	SERIAL NUMBER (List simulator S / N also) FIELD LOCATION						
8110107	INTOX: 80	.000312	SIMULATOR:	_	GOODYEAR	PP	
DPS EQUIPMENT NUMBER	SUMBITTING A	GENCY'S FULL NAME (NO	DINITALS)		<del></del>	<del></del>	
QUALITY ASSURANCE SPECIA		^ .			PHONE NUMBER		
		BF/1 W	$I_1I$	1.0	( )		
QUALITY ASSURANCE SPECIALIST MAILING ADDESS CITY STATE ZIP CODE							
Was a S.Q.A.P. completed p	nor to removal fr	om service?					
No, Explain:	_		_				
Yes, Date: Date out of service:							
☐ No ☐ Yes Do records need to be downloaded (ACTIVE C.O.B.R.A., ONLY)							
EQUIPMENT SENT:			<del> </del>				
	WER CORD	BREATH HOSE	EXTERNAL PRINTER	SIMULATOR	☐ KEYBOARD	Пиореи	
<u> </u>		_	=	☐ SIMODATOR	LT KEAROWKD	MODEM	
HEATED SIMULATOR TI		BRACKET	OTHER				
PROBLEM DESCRIPTION: (WI	nat is the instrumer	nt doing or not doing? Inclu	de observations such as processor	errors or other display	ed messages.)		
	RAM	~ FAIL					
				<del>_</del>			
				<del></del>			
						<del>_</del>	
	<del></del>				<del></del>		
					<del></del>		
			AB USE ONLY				
CORRECTIVE ACTION	<b>20</b> 0			<u> </u>			
	KeplA	t Mo	THA BUANT	<u>/</u>	<del> </del>	_ <del>_</del>	
	Re-C	ALFBRAT	e Fucr	ION CH	ech		
<u> </u>					·		
			<del></del>	<del></del>			
					<del>-</del>		
ļ							
		<del></del>			<del></del>		
				<del></del>			
	<del></del>	<del></del>					
COMMENTS							
COMMENTS							
					<del></del>	<del></del>	
A							
/							
			DADOE AID NO. TITLE		DATE		
TECHNICIAN'S NAME	1	// _)	BADGE / ID NO. TITLE		DATE	1- ~	
/// M	//	7'		· recit	10/15,	<u>′0 / </u>	
CALLED FOR PICKUP		DATE	CONTACT PERSON				
X			1				

INTOXILYZER 9000 Location: GOUDYEAR PO Serial Number: 80-000312

10/15/2007

10:00:30

Standard Lot#: 7065021

Last Changed By: J. SLGWINSKI #6181

QAS: #

Operator: j. SLOWINSKI #610!

AZ DPS

Subject: FOUR, SAMPLE, T DOB: 03/01/1965 Sex: M Weight: 150

15 Minute Deprivation Period? Yes

Test	g/2!0L	Time
Air Blank	0.000	10:01:11
Diagnostic Test	Pass	10:01:40
Air Blank	0.000	10:02:07
0.100 Cal Check	0.095	10:02:26
Air Blank	0.989	10:02:55
Subject Test	0.189	10:03:26
Air Blank	8.000	10:54:91
Five Minute Wait	D 000	18 80 50
Air Blank	D. 000	10:08:53
Subject Test	0.191	10:09:10
Air Blank	0.000	10: 89: 43
0.100 Cal Check	0.091	10:10:02
Air Blank	8.030	10:10:31
Diagnostic Test	Pass	10:11:00

Successfully Completed Test Sequence