EXHIBIT G-2 THIS REPORT PREPARED PURSUANT TO DUTY IMPOSED BY A.A.C. R13-10-104 (A)

ARIZONA DEPARTMENT OF PUBLIC SAFETY

STANDARD QUALITY ASSURANCE PROCEDURES INTOXILYZER MODEL 8000

STANDARD CALIBRATION CHECK PROCEDURE

QA SPECIALIST W. T. KYAN 1100 AGENCY GOODYGAR POLICE DEA
DATE 2-1-2019 TIME 1444 HRS
INTOXILYZER SERIAL # 90-0003/2 LOCATION // N /4574 AVE GOODVE
1. Ensure that gas tank is attached to instrument and contains a standard alcohol concentration solution 0.100 AC
Pour a standard alcohol concentration solutionAC, into a clean dry simulator and assemble the simulator. Ensure that a tight seal has been made. Turn on the simulator and allow temperature to reach 34°C ± 0.2°C
 2. Intoxilyzer 8000 display reads "PUSH BUTTON TO START" 3. Go to the "Control Testing Menu". Select "D" for dry control test or "W" for wet control test. After selection is
4. Air blank completed. 5. Calibration check completed. Test results 0. 098 AC. 6. Air blank completed. 7. Remove printed record. Attach the record attach
7. Remove printed record. Attach the record to the completed checklist.
SIGNATURE (1). T. Regan 1100
OPS Form Exh G-2 (Rev 05-01)

INTOXILYZER 8000

Location: 11 N 145TH AVE Serial Number: 80-000312 Core Version: 8105.48

14:44:25 02/01/2019 -----

Standard Lot#: 10818100A1

Last Changed By: W. RYAN #1100

QAS: W. RYAN #1100

GOODYEAR PD

Operator: W. RYAN #1100

GOODYEAR PD

g/210L	Time
0.000	14:44:57
0.098	14:45:18
0.000	14:45:48
	0.000

Preventative Maintenance Performed -- Timer Reset