## EXHIBIT G-2 THIS REPORT PREPARED PURSUANT TO DUTY IMPOSED BY A.A.C. R13-10-104 (A)

## ARIZONA DEPARTMENT OF PUBLIC SAFETY

## STANDARD QUALITY ASSURANCE PROCEDURES INTOXILYZER MODEL 8000

## STANDARD CALIBRATION CHECK PROCEDURE

(1)
QA SPECIALIST K-MIYAZITO AGENCY (78074 SAR
DATE 7/1 (2000 TIME 0336
INTOXILYZER SERIAL # 80 - 001858 LOCATION // N/45 TH AVE
1. Ensure that gas tank is attached to instrument and contains a standard alcohol concentration solution OR
Pour a standard alcohol concentration solutionAC, into a clean dry simulator and assemble the simulator. Ensure that a tight seal has been made. Turn on the simulator and allow temperature to reach 34°C ± 0.2°C
2. Intoxilyzer 8000 display reads "PUSH BUTTON TO START" 3. Go to the "Control Testing Menu". Select "D" for dry control test or "W" for wet control test. After selection is made press ENTER.
4. Air blank completed. ( ) 5. Calibration check completed. Test results 0. AC.
6. Air blank completed. 7. Remove printed record. Attach the record to the completed checklist.
SIGNATURE 135
DPS Form Exh G-2 (Rev 05-01)

INTOXILYZER 8000

Location: 11 N 145TH AVE Serial Number: 80-001858 Core Version: 8105.48

07/01/2020

03:36:23

1. ~

-----

Standard Lot#: 07919100A1

Last Changed By: K. MIYAZATO #1139

-----

QAS: K. MIYAZATO #1139

GOODYEAR PD

.....

Operator: K. MIYAZATO #1139

GOODYEAR PD

-----

Test	g/210L	Time
Air Blank	0.000	03:37:05
0.100 Cal Check	0.099	03:37:26
Air Blank	0.000	03:37:55

Preventative Maintenance Performed -- Timer Reset