

ARIZONA DEPARTMENT OF PUBLIC SAFETY

INTOXILYZER MAINTENANCE REPORT

CR NO. 1900037950002

Page 1 of 1

AGENCY Goodyear Police Department

Goodyear, AZ 85338

OFFICER MIYAZATO, #1139 DATE

November 21, 2022

INSTRUMENT

90003795

INSTRUMENT LOCATION

Goodyear Police Department

MAINTENANCE REQUESTED

Repair

MAINTENANCE PERFORMED

Parts Replaced:

Breath Hose

Jush m 1 -

JOSEPH M SLOWINSKI, #6101, Forensic Services

Technician

Central Regional Crime Laboratory

2102 W. Encanto Blvd., Phoenix, AZ 85009