



ARIZONA DEPARTMENT OF PUBLIC SAFETY

INTOXILYZER MAINTENANCE REPORT

CR NO. I800018580012

Page 1 of 1

AGENCY Goodyear Police Department
 Goodyear, AZ 85338
OFFICER MIYAZATO, #1139
DATE July 07, 2023



INSTRUMENT

80001858

INSTRUMENT LOCATION

Goodyear Police Department

MAINTENANCE REQUESTED

Repair and Preventative Maintenance

MAINTENANCE PERFORMED

Parts Replaced:

Battery

Power Fuse

Preventative Maintenance Performed:

Inspection, Calibration, Verification

Erin E Boone

ERIN E. BOONE, #5823, Forensic Scientist
Central Regional Crime Laboratory
2102 W. Encanto Blvd., Phoenix, AZ 85009
602-223-2281 eboone@azdps.gov