



ARIZONA DEPARTMENT OF PUBLIC SAFETY

INTOXILYZER MAINTENANCE REPORT

CR NO. 1900046050002

Page 1 of 1

AGENCY Goodyear Police Department
Goodyear, AZ 85338
OFFICER MIYAZATO, #1139
DATE September 23, 2024



INSTRUMENT

90004605

INSTRUMENT LOCATION

Goodyear Police Department

MAINTENANCE REQUESTED

Repair and Preventative Maintenance

MAINTENANCE PERFORMED

Parts Replaced:

Breath Hose

Preventative Maintenance Performed:

Inspection, Calibration, Verification

A handwritten signature in black ink, appearing to read "Aleksis Croci".

ALEKSIS CROCI, #11246, Forensic Scientist
Central Regional Crime Laboratory
2102 W. Encanto Blvd., Phoenix, AZ 85009
(602) 223-2394 acroci@azdps.gov