

EXHIBIT I-2  
THIS REPORT PREPARED PURSUANT TO DUTY IMPOSED BY A.A.C. R13-10-104 (A)

ARIZONA DEPARTMENT OF PUBLIC SAFETY  
INTOXILYZER MODEL 9000

PERIODIC MAINTENANCE AND STANDARD QUALITY ASSURANCE PROCEDURE

QA SPECIALIST K Miyazato 1139 AGENCY Goodyear  
DATE 10/31/24 TIME 10143  
INTOXILYZER SERIAL # 90-004605

1. Ensure that gas tank is attached and contains a standard alcohol concentration -100 AC

DIAGNOSTIC TESTS

1. Clock time check  
 2. Date check

OPERATIONAL TESTS

1. Deficient Subject Test (Proper Sample Recognition)  
Deficient Sample printed
2. Alcohol-free Subject Test (Proper Sample Recognition):  
0. 000 AC
3. Mouth Alcohol Subject Test (Proper Sample Recognition):  
Invalid Sample – Begin new deprivation period printed
4. Radio Frequency Interference Test (Error Recognition):  
RFI Detect printed
5. Standard Calibration Check:  
0. 101 AC
6. Air Blanks Completed
7. Timer Reset

Not a Successfully Completed Test Sequence will be printed

Instrument is operating properly and accurately. YES  NO

COMMENTS:

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

SIGNATURE KM 1139

# ARIZONA FORENSIC BREATH ALCOHOL ANALYTICAL REPORT

## INSTRUMENT INFORMATION

Analytical Instrument: Intoxilyzer 9000  
Serial Number: 90-004605  
Software Version: 9439.01.00  
Analytical Report Number: 46051031240237

QAS: MIYAZATO, KORY  
QAS Permit #: 30215  
Agency: GOODYEAR PD  
Last 31-Day Check: 09/30/2024  
Last Annual Maintenance: 09/20/2024

## SUBJECT INFORMATION

Name: 31-Day Check  
Test Date: 10/31/2024  
Driver's License #:  
Gender:  
Date of Birth:  
Age:

Weight:  
State of Issue:  
Driver's License Expiration:  
Deprivation Start Time: 01:15  
15 - Minute Deprivation: Yes

## OPERATOR INFORMATION

Name: MIYAZATO, KORY  
Agency: GOODYEAR PD

Permit #: 30215  
STANDARD INFORMATION  
Standard Value: 0.100  
Standard Lot #: 24923100A1  
Expiration Date: 10/05/2025  
Bottle #: 52  
Last Changed By: MIYAZATO, KORY

Permit #: 30215

<u>Test</u>	<u>g/210L</u>	<u>Time</u>
Air Blank	0.000	01:43:50
Diagnostic Test	PASS	01:44:26
Air Blank	0.000	01:45:03
Calibration Chk	0.102	01:45:25
Air Blank	0.000	01:46:04
Subject Test 1	DEF*	01:49:17
Air Blank	0.000	01:49:59
Air Blank	0.000	01:50:39
Subject Test 2	0.000	01:50:57
Air Blank	0.000	01:51:37
Wait		01:55:40
Air Blank	0.000	01:56:17
Subject Test 3	INV**	01:56:36
Air Blank	RFI***	01:56:54

## RESULTS

\*Deficient Sample  
\*\*Invalid Sample - Begin new deprivation period  
\*\*\*RFI Detect

## EXCEPTION MESSAGES

\* Deficient Sample  
\*\* Invalid Sample - Begin new deprivation period  
\*\*\* RFI Detect

## OPERATOR COMMENTS

Not a Successfully Completed Test Sequence

*All air blank results must be 0.000.  
Consecutive subject test results must not differ by more than 0.020 g/210L.  
Standard check results must be ±10%.*

**Intoxilyzer - Alcohol Analyzer**

**Model 9000**

**SN: 90-004605**

**Test Date: 10/31/2024**

**Test Time: 01:57**

**Location:**

**Software Version: 9439.01.00**

**Standard Lot #: 24923100A1**

**Standard Value: 0.100**

**Expiration Date: 10/05/2025**

**Bottle #: 52**

**Last Changed By: MIYAZATO, KORY**

**Permit #: 30215**

**Operator: MIYAZATO, KORY**

**Permit #: 30215**

**Agency: GOODYEAR PD**

<u>Test</u>	<u>g/210L</u>	<u>Time</u>
Air Blank	0.000	01:57:44
Calibration Chk	0.101	01:58:06
Air Blank	0.000	01:58:46

**No RFI Detected**